ULTRATECH INTERNATIONAL, INC.

Products for a cleaner, safer, and more sustainable world.™

NOTICE: Replacement Program for Containment Bladders Used in Ultra-Spill Deck, Ultra-Inline Spill Deck, Ultra-Decon Deck, Ultra-Safety Cabinet, and Ultra-Pop Up Pool Plus Products

September 11, 2026

To Whom It May Concern,

We recently identified a manufacturing issue affecting the containment bladders used in the products listed below. Working with our supplier, we traced the issue to damage to a sealing component on the production equipment, which resulted in weak seams on some bladders. An affected bladder may not hold liquid as intended when filled.

To resolve this, we are providing free replacement bladders to all affected customers, along with simple instructions for installing them. Other than the time it takes to install the replacement, there is no cost to you or your customers.

Affected Product

The affected bladders carry the following batch numbers:

066274, 066159, 066026, 065862, 065861, 065859, 065595, 062685, 062466, 062274, 062264, 062225, 062027, 061887

The batch number is printed on a white label affixed directly to the bladder. If the bladder is still in its original packaging, the label can be found on the bladder inside the box.

Product containing these bladders was sold between 10/01/25 and 12/31/25, and between 07/01/26 and 08/31/26. Bladders produced since the equipment was repaired have been tested and are not affected.

The following part numbers should be checked:

Part No.	Description
1320	Ultra-Spill Deck Bladder System, P1 Bladder System - 1-Drum
1359	Ultra-Spill Deck, Flexible Model - Replacement Bladder
1360	Ultra-Spill Deck, P1 Bladder System - 1-Drum
1361	Ultra-Spill Deck, P2 Bladder System - 2-Drum
1362	Ultra-Spill Deck, P4 Bladder System - 4-Drum
2317	Ultra-Spill Deck, Bladder Attachment
2329	Ultra-Spill Deck Bladder System, P2 Bladder System - 2-Drum
2330	Ultra-Spill Deck, P4 Bladder System - 4-Drum
2333	Ultra-Inline Spill Deck, 5-Drum Model
2360	Ultra-Inline Spill Deck, 3-Drum Model - 3-Drum
2361	Ultra-Inline Spill Deck, 4-Drum Model - 4-Drum
2420	Ultra-Safety Cabinet Bladder Systems, 1-Drum Model - 1-Drum
2421	Ultra-Safety Cabinet Bladder Systems, 2-Drum Model - 2-Drum
6340	Ultra-Decon Deck, Replacement Bladder - For P/N 2317

Part No.	Description
6345	Ultra-Decon Deck, Replacement Bladder - 5.75"
8010	Ultra-Pop Up Pool, Plus Model - 20 Gallon
8012	Ultra-Pop Up Pool, Plus Model - 66 Gallon
8016	Ultra-Pop Up Pool, Plus Model - 150 Gallon

What We Are Asking You To Do

Discontinue use of any affected bladder. An affected bladder should not be relied upon for containment until it has been replaced. If an affected unit is currently deployed and holding liquid, transfer the contents to another containment unit as soon as it is safe to do so.

Hold your stock and send us a count. Please place any inventory of the part numbers above on hold and do not ship it. Report your on-hand quantity by part number, regardless of when it was purchased. We will issue a return authorization and replacement stock at no charge, including freight in both directions.

Contact your customers who purchased the affected parts between 10/01/25 and 12/31/25, or between 07/01/26 and 08/31/26. Direct them to the address below, where they can check their batch number against the affected list and request a free replacement:

https://spillcontainment.com/brr

A separate request should be submitted for each affected part number. We will ship a replacement bladder directly to the address provided, along with installation instructions.

Corrective Action

We had quality control processes in place covering this product, and this issue was not caught before the affected bladders shipped. We take that seriously. Beyond repairing the equipment, we have implemented additional inspection and pressure testing requirements on bladders before they are released, along with revised preventive maintenance and verification requirements at the production facility, so that a fault of this kind is identified before product ships again.

Questions

Your customers may contact us directly at (904) 292-1611 for more information, or you may reach out to your UltraTech representative. We appreciate your attention to this matter and your help in getting replacements to the customers who need them.

Thank you,

Matthew Shaw

Chief Operating Officer
UltraTech International, Inc.